



Mrs J Nolan
Clerk to the Council

The Parish Council Community Centre
Bell Lane, Ackworth
Pontefract, WF7 7JH

Tel: 01977 611583

E-mail: clerk@ackworthparishcouncil.gov.uk

8 April 2024

Sent via email to [@gmail.com](#)

Dear

Freedom of Information Request – Carr Bridge Playground Ancillary Items

I write in response to your Freedom of Information request dated 8th April 2024.

Under the freedom information, please can I also have a copy of the most recent annual Health and Safety Inspection Report which covers the fence and the gate (which surrounds the play equipment) and the gate post, seating, bin etc regarding Carr Bridge Park as this should also have been incorporated in the original Report.

Please see Appendix 1 below for the report page which contains this information as per your request.

I can confirm the report you were provided back in February 2024 is the latest report.

The items requested today are ancillary items not play equipment which is why they were not included as part of the original Freedom of Information response.

If you are unhappy with the way your request for information has been handled, you have a right to appeal to the Information Commissioner by phone 0303 123 1113 or website <https://ico.org.uk/>

There is no charge for making this request.

Yours sincerely

Jemma Nolan
Clerk to the Council

Appendix 1.

CARR BRIDGE PLAYING FIELD

Ancillary items/Comments

- Seats x three – within 1m of fence (**Low Risk**)
- Litter Bin x one satisfactory (**Very Low Risk**)
- Sign satisfactory (**Very Low Risk**)
- Fence (around items 6-14 only) – potential neck trap at bow tops & seat within 1m (**Medium Risk**) Anti-sag bars not fitted – monitor
- Pedestrian Gate x one – **clearance of between 60mm & 110mm should be maintained at bottom of gate (actually 45mm). Slight distortion of gate – requires attention. (Low Risk) Re-adjust self-closing device as gate closing too fast (closing in 3.5 seconds, should be at least 5 seconds) (Medium Risk)**
- Only one pedestrian entrance (**Medium Risk**)
- Path satisfactory (**Very Low Risk**)
- General area – good condition. Tidy

MEDIUM RISK SITE
